



## Key Notes

- 1 Existing playground equipment is removed and new playground equipment is located in the central activity area.
- 2 Some CWS buffers are planted and a mitigation trade area is established. Open views are provided through the buffer vegetation to promote safety and security from Pioneer Road.
- 3 The eastern half of the existing sports court is modified to create a central plaza with drinking fountain and picnic area. The ball wall is removed and a new ball wall is added to the western court. Bike racks are included in the plaza.
- 4 The large central lawn is preserved with the addition of trees along the creek for resource enhancement.
- 5 The southern trail access and bridge are relocated to align with the plaza. Creek improvements are made around the bridge.
- 6 A Boardwalk is placed over the western crossing on the central creek.
- 7 All trails are paved south of the mid-forest trail, connection. To the north the trail will be a soft surface. The main entrance trail from Meadow Road to west boardwalk is widened for maintenance access.
- 8 The southeast entrance has a new entrance pathway and accent planting.
- 9 Future Trail Connection to the Westside Trail.
- 10 A picnic table is added at the edge of the forested area.
- 11 A trail connects the existing sidewalk with the path to the bridge.